

PHOTO #151

ROUTINE INSPECTION

UP TO 3'-0" LONG x 1'-4" WIDE (WEST FACE) x FULL HEIGHT x 6" DEEP SPALL/DELAMINATION WITH EXPOSED AND BROKEN REBAR AND EXPOSED POST TENSION ANCHORS

1'-0" WIDE x 7" LONG REDUCED BEARING AREA



CANTILEVER GIRDER 'A' - NORTH FACE AT PIER #7 IN SPAN #7 (LOOKING SOUTH)

BRIDGE #070001

07/21/2023

**JULY**  
Inspection



Photo #3

Failed tiedown

Steel rod sheared at top



Cantilever A North Face at Pier 7 (Looking South)

Bridge # 070001

12/08/2023

**DECEMBER**  
Inspection

PHOTO #152

ROUTINE INSPECTION



CANTILEVER GIRDER 'F' – SOUTH FACE AT PIER #7 IN SPAN #7 (LOOKING NORTH)

BRIDGE #070001

07/21/2023

**JULY**  
Inspection



Photo #8



Cantilever F South Face at Pier 7 (Looking North)

Bridge # 070001

12/08/ 2023

**DECEMBER**  
Inspection